

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer)
(Re: G.O Ms. 20/70/PWD Dt. 23-01-1970)

Name of the School

EKC Public School Manjeri

1 Name of the Officer

BAIJU K , ASSISTANT ENGINEER

2 Location with Name of Education District

Cherukulam - Malappuram

3 Period for which the Certificate is issued

2026-27

4 Types of building

Details of Building

5 Nature of defects, if any

No.

Permanent RCC Building

a) Foundation and basement

Nil

GF: 8.40x6.30 m (2 Class Room)

b) Superstructure

Nil

FF: 8.40x6.30 m (2 Class Room)

SF: 8.40x6.30 m (3 Class Room)

c) Doors & Windows

Nil

10.12x4.42 m (1 Class Room)

d) Wood work wrought and put up.

Nil

5.88x4.42 m (1 Class Room)

e) Roof

Nil

f) Flooring

Nil

g) Miscellaneous (Craks if any)

Nil

6 Any major defects notices which will render the building unsafe if any manner

No major defects were found during site inspection.

7 Whether maintenance work have been done properly.

Yes

8 Whether the structure is sound or not for Conducting classes

Sound and fit for conducting classes under Normal weather and climatic condition.

Note:-

- 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind expourse to flood etc.
- 2 Any additional observation if deemed necessary for the certificate may be furnished separately with the Certificate.
- 3 The electrical wiring in the shool building shall be examined by a approved/licensed wireman within one month
- 4 The Headmaster/Applicant should obtain all the relevant NOCs from the various department as per the circular No: M3/347/2019- health dated 09/11/2025

CERTIFICATE

Certified that the School was inspected by me on 30/05/2026 and found to be **Fit** to conduct classes for the period 2026 - 27 for the reasons stated above.

Place : Thrikkalangode

Date : 30/05/2026



[Signature]
ASSISTANT ENGINEER
LSD Section, Thrikkalangode-GP
P.O Karakkunnu Pin: 676 123

Remarks:

1. Steps to regularize unauthorized constructions if any, should be taken within two months.
2. Additional maintainance should be done for the damaged pillers and steps to be taken to remove the unuseful materials from the school compound